



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization	Mandatory Information Required
Company Name	Mobil Producing Nigeria -MPN
Reporting Officer	Mark Fraser
Designation	General Manager, Joint Venture Operations
Phone Number	0817 206 8193
Email Address	mark.w.fraser@exxonmobil.com
Incident Number	22 / 2022
Section 2 - Location	
State / LGA	Ubit PP OML 67 - /
Coordinates of spill	EASTINGS 4Deg 15Min/32Secs N NORTHINGS 8Deg 11Min/5Secs E
	☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others
Depth of Water (if applicable)	
Section 3 – Spill Details	
Date and Time of spill	12/14/2022 Time: 12:00 hours local time
Source of spill – Facility	TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☒ Pipeline PIPELINE (Specify pipeline diameter) ☐ Trunkline ☒ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....
Cause of spill	Equipment Failure, Corrosion: At about 1200hrs Powertrim personnel (vendor executing risk based coating) reported to the control room of a pin hole leak resulting from the blasting activities around the 6" metering line FE-053 on Separator D.
Status of spill	☒ Contained ☐ Not Contained ☐ Unknown
Containment Measures in Place	☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify)... IMMEDIATE RESPONSE *Suspended blasting activities at the area and moved personnel out of location. *Provided containment at leak point and applied absorbent to mitigate sheen spread. *Installed a 6-inch clamp on the pin hole leak point on metering line FE-053 to stop the leak.

		CORRECTIVE ACTIONS / NEXT STEPS *Review surface preparation options to continue coating in vulnerable sections. *Fabricate piping replacement spool and execute permanent repairs.....	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		
	Wax Content		
	Asphaltene		
	Sulphur Content		
	Viscosity		
Oil	Slick Locations(s)		

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		
Surveillance Method		☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat ☒ On site ☐ Others.....	
Section 4 – Approximate Duration			
Release Rate	Instantaneous Release		Continuous Release
		Per Hour	☐ Hours ☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.01409 bbl. of crude oil based on sheen appearance	
	Coverage	About 40m x 25m of 40% silvery sheen, 20% light brown & 40% rainbow colors as appeared on sea water	
	Direction of travel	South East	
Section 5 - Weather			
METEOROLOGICAL DATA			NIMET weather forecast
Wind Direction (wind direction given from)	South East		
Initial Wind Speed	15 Knots		
Air Temperature (C or OF)	31 C		
Visibility Estimate	☒ Good ☐ Fair ☐ Poor		
OCEANOGRAPHIC DATA			
Water Current Speed			
Tide Phase: Flood	High ☐	Ebb ☐	

Additional information (please use start date and time)	

DS
1E

DESIGNATION: General Manager, Joint Venture Operations.....

**RBA Report must be submitted within 24 Hours of the Spill Incidence.*