



National Oil Spill Detection and Response Agency

FORM A

OIL SPILL NOTIFICATION REPORT

This report must be submitted within 24 hours of Spill Incidence

Section 1 – Site Organization		Mandatory Information Required	
Company Name		Mobil Producing Nigeria -MPN	
Reporting Officer		Mark Fraser	
Designation		General Manager, Joint Venture Operations	
Phone Number		+2348172068193	
Email Address		mark.w.fraser@exxonmobil.com	
Incident Number		018 /2023	
Section 2 - Location			
State / LGA		Ubit PP OML 67 - / Akwa Ibom State	
Coordinates of spill		EASTINGS 4Deg 16Min/26Secs N NORTHINGS 8Deg 10Min/33Secs E	
		☐ Inland ☐ River ☐ Mangrove ☐ Shoreline ☐ Port ☐ Harbour ☒ Offshore ☐ Subsea ☐ Swamp Area ☐ Others	
Depth of Water (if applicable)			
Section 3 – Spill Details			
Date and Time of spill		12/4/2023 Time: 07:00 hours local time	
Source of spill – Facility		TRANSPORTATION FACILITIES ☐ Ocean Tanker /Ship ☐ Tank Truck ☐ Barge ☐ Tanker Vessel ☐ Pipeline At about 0700hrs, silvery surface was observed around Ubit GP North West which was traced to the OOS 16" Idoho pipeline riser PIPELINE (Specify pipeline diameter) ☐ Trunkline ☐ Flowline ☐ Bulkline ☐ Export line ☐ Gas Line STORAGE TANKS ☐ Underground Storage Tanks ☐ Above-Ground Storage Tanks ☐ Others (specify)..... PRODUCTION FACILITIES ☐ Well head ☐ Manifold ☐ Flow station ☐ Oil Rig ☐ Compressor Plant ☐ FPSO ☐ Refinery ☐ Others.....	
Cause of spill		Corrosion: At about 0700hrs, silvery surface was observed around Ubit GP North West which was traced to the OOS 16" Idoho pipeline riser	
Status of spill		☒ Contained ☐ Not Contained ☐ Unknown	
Containment Measures in Place		☐ Boom ☐ Skimmer ☐ Trenches ☐ Bund wall ☐ Sorbent ☒ Others (specify): Less than 50cl of dispersant was applied and the sheen dispersed due to turbulent wave movement at that time. The team is currently progressing plans to repair corroded sections of the riser with composite wrap.	
Product Data	☐ Persistent		☐ Non Persistent
	Product Name/Type		
	SG/API Gravity		
	Pour Point		

	Wax Content		
	Asphaltene		
	Sulphur Content		
	Viscosity		
Oil	Slick Locations(s)		

observation	Slick Dimension(s)		
	Orientation of slick(s)		
	Distribution of oil		
	Obvious odour		
Oil descriptions	Tarballs (tb)		
	Convergence line (co)		
	No structure (ns)		
	Windrows (wr)		
	Streamers (st)		
	Patches (pa)		
Oil color and appearance	Silver/grey		
	Rainbow		
	Metallic		
	Transitional		
	Dark		

Surveillance Method ☐ UAV (Drone) ☐ Satellite imagery ☐ Aircraft ☐ Boat
☐ On site ☐ Others.....

Section 4 – Approximate Duration

Release Rate	Instantaneous Release	Continuous Release		
		Per Hour	☐ Hours	☐ Days
Description of observed spill	Estimated Quantity (bbl)	About 0.00021 bbl of Oily Water based on sheen appearance		
	Coverage	At about 0700hrs, silvery surface was observed around Ubit GP North West which was traced to the OOS 16" Idoho pipeline riser		
	Direction of travel	North West		

Section 5 - Weather

METEOROLOGICAL DATA

Wind Direction (wind direction given from)		NIMET weather forecast
Initial Wind Speed		
Air Temperature (C or OF)		
Visibility Estimate	☒ Good ☐ Fair ☐ Poor	

OCEANOGRAPHIC DATA

Water Current Speed		
Tide Phase: Flood	High ☐ Ebb ☐	
Water Temperature (OC or OF)		
High Tide Time		
Source		

Section 6 – Pre-Entry Activities

Mechanical cleaning	Yes ☐ No ☐
Recovery of free phase oil	Yes ☐ No ☐
Booming	Yes ☐ No ☐
Wild life rehabilitation	Yes ☐ No ☐
Dispersant application	Yes ☐ No ☐

Section 6 – Pre-Entry Activities			
Spill Trajectory Modeling	Surface 2D ☐	Sub-Surface 3D ☐	Not at this time ☐

Additional information (please use start date and time)

Section 8– Equipment	
On Site	

REPORTING OFFICER: Mark Fraser
DESIGNATION: General Manager, Joint Venture Operations

DS
 DocuSigned by:
Mark W. Fraser
E80C423DA74246A...
SIGNATURE: **DATE:** December 5, 2023

*RBA Report must be submitted within 24 Hours of the Spill Incidence.