

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation. The affected pipeline has been repaired with evidence of burnt vegetation. Effective security surveillance should be ensured and more marker posts be put in place.

12. Time investigation ended..... 1650HRS