

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... *N/A*

10. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation..... *The affected pipeline has been repaired. More marker posts should be installed and security surveillance intensified and the repaired points should be backfilled.*

12. Time investigation ended..... *1720HRS*