



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NADC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) _____

3. Incident Details

- i. Date of Incident: 27/10/2018 ii. Date first reported: 27/10/2018
iii. Date of first investigation: 9/11/2018
iv. Date of follow-up investigation: NIL
v. Time investigation started: 14:35 HRS
vi. Estimated quantity spilled: 3.67 bbls

4. Site Details

- i. Site Location: OBRIKOM IS MINI-MANIFOLD, OBIAFU FIELD, OBRIKOM.
ii. Position of Spill/Leak: N 05° 24' 52.6" E 006° 36' 23.4"
iii. Spill area:
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify): SEASONAL SWAMP
iv. Structural Controls in Place:
☒ Dike ☐ Embankment ☐ Flood Wall ☐ Substrate ☐ Others (Specify) _____

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 1 O'Clock
☒ 4 O'Clock ☒ 3 O'Clock ☒ 6 O'Clock 5-8 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) _____

iii. Facility

- ☐ Pipeline ☐ Flow Line ☐ Wellhead ☒ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify) _____

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) _____

v. Visible Sign of Third Party Interference

- ☒ Truck/Machine Marks ☐ Drilled Holes ☐ Mining ☐ Theft ☐ Acid
☐ Others (Specify) _____

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) _____

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☒ Withering of vegetation ☐ Others (Specify) _____

iii. Delineation of Impacted area

- ☐ Within Company's facility R/W ☒ Outside Company's facility R/W

Extent of Impact

(a) Community (Indicate names)

(b) Land (Indicate area in m²)

2170-97m²

(c) Creek/Creeklets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph Map Chart Ref.

☒ All photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ For ☐ On ☐ At

11. Remarks/Recommendation: Repair was carried out immediately after
TIV. Immediate clean-up of impacted area required. Sur-
veillance should be improved within the manifold.

12. Time Investigation ended.....

13. Name and Signature of Participant.....

14. NOSDR-