

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT



Fig A: Incident Area on arrival of the JIT



Fig B: Oil spill impacted area



Fig C: Incident Facility after excavation



Fig D: Incident facility during repair