


ix. Repair work (patch welding) was concluded on January 22, 2018.

7.0 PHOTOGRAPHS TAKEN:



A

FIG A: Site on arrival along right of way



B

FIG B: Letters pinned to a board along RO



C

FIG C: Incident point with IED



D

FIG D: Oil and Gas scouring the site



E

FIG E: Incident point on exposure



F

FIG F: Incident point on full exposure