

- i. On arrival at the site, the team saw some of the vandals along the pipeline right of way though at a little distance.
- ii. The military had to fire a couple of gunshots and combed the bush before the team could commence work which was a little scary.
- iii. Crude impact was mainly within the Company right of way, impacting an estimated 694 m².
- iv. The spill was as a result of unknown persons installing a 2" valve on the pipeline at 12 O Clock position for oil theft.
- v. Repair work (coning) was concluded on January 24, 2018.

7.0 PHOTOGRAPHS TAKEN:



A

FIG A: Incident point




B

FIG B: Environment of impact



C

FIG C: Incident point after exposure



D

FIG D: Incident point after repairs