



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company: EROTON

2. Type of Complaint/Incident:

- ☐ Oil Pollution      ☐ Fire/Explosion      ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) .....

3. Incident Details

- i. Date of Incident: 09/07/2018      ii. Date first reported: .....  
iii. Date of first investigation: 12/07/2018 .....  
iv. Date of follow-up investigation: 15/07/2018 .....  
v. Time investigation started: 12:00hrs .....  
vi. Estimated quantity spilled: 14 BBLs .....

4. Site Details

- i. Site/Location: CANTHURNE CHANNEL III AKASO WELL HS 4" FLOWLINE  
ii. Position of Spill/Leak: N 4° 33' 1.4" E 6° 58' 34.70"

iii. Spill area

- ☐ Land      ☒ Swamp      ☐ Freshwater      ☐ Mangrove      ☐ Coastline  
☐ Near shore      ☐ Offshore      ☐ Others (Specify) .....

iv. Structural Controls in Place

- ☒ Boom      ☐ Trenches      ☐ Bund Wall      ☐ Sorbents      ☐ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock      ☐ 10 O'Clock      ☐ 2 O'Clock      ☐ 3 O'Clock  
☐ 4 O'Clock      ☐ 5 O'Clock      ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil      ☐ Condensate      ☐ Chemicals      ☐ Refined Products  
☐ Others (Specify) .....

iii. Facility

- ☐ Pipeline      ☒ Flow Line      ☐ Wellhead      ☐ Manifold      ☐ Flow Station      ☐ Rig  
☐ Storage Tank      ☐ Compressor Plant  
☐ Others (Specify) .....

iv. Cause of Spill

- ☐ Corrosion      ☐ Equipment Failure      ☐ Third Party Interference      ☐ Accident  
☐ Operational Error      ☐ Others (Specify) FLOW LINE THEFT

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks      ☐ Drilled Holes      ☐ Blasting      ☐ Theft      ☐ Acid  
☐ Others (Specify) 570 metres of the flowline was hacked