

Inc. No. 2019/LAR/051/088

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: MAUC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

i. Date of Incident: 26/09/19 ii. Date first reported:

iii. Date of first investigation: 28-09-19

iv. Date of follow-up investigation:

v. Time investigation started: 10:43 AM

vi. Estimated quantity spilled: 10.06 bbl (9.56 bbl recovered)

4. Site Details

i. Site/Location: 24" Ogele/Bass p/k @ Obochi

ii. Position of Spill/Leak: N 05° 00' 45.1" E 006° 31' 56.9"

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☒ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (Specify) 4" Ball valve seen installed

@ 12 o'clock position

6. Impact of Incident

i. Properties Impacted by the Incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of Impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) *burnt vegetation*

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i. *20 sqm for pit*
 ii. *2650 sqm of fire impact*
 iii.
 iv.

(c) Creek/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>
<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>
<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>

(d) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>
<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>
<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>

(e) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>
<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>
<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>

(f) Shoreline/water

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>
<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>
<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>	<i>[scribble]</i>

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☒ Mapping

9. Samples taken N/A

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation

The site was on fire when the team arrived. Fire was successfully put out. Vegetation was burnt. A 4" valve was seen installed on P/L for theft purpose. Repairs were effected.

12. Time investigation ended

13.15 hrs.

13. Name and Signature of Participants