

2405092



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 20/07/2019 ii. Date first reported:
iii. Date of first investigation: 22/07/2019
iv. Date of follow-up investigation: 23/07/2019
v. Time investigation started:
vi. Estimated quantity spilled: 3 BARRELS

4. Site Details

- i. Site/Location: 18" ASSA - RUMUEKPE PIPELINE AT EGBEDA
ii. Position of Spill/Leak: N 5° 13' 50.4" E 6° 46' 4.2"

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets
☐ Dead floating crabs ☒ Withering of vegetation

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. ECRSDA

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i. 600

ii.

iii.

iv.

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☒ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....

JIV CONDUCTED SUCCESSFULLY.
SPDC SHOULD INTENSIFY SURVEILLANCE ALONG
THE PIPELINE. IMPACTED AREA SHOULD BE CLEANED-UP
IMMEDIATELY.

12. Time Investigation ended.....