


APPENDIX 1




SPILL POINT ON ARRIVAL.



3" VALVE INSTALLED ON THE LINE.



THE POINT WAS CONED.



REPAIRED POINT.