


APPENDIX 1



SPILL POINT ON ARRIVAL.



LEAKING CRUDE OIL STORAGE BARGE.



AREA AROUND TAKWA BEACH.



OIL ON WATER BODY AND VEGETATION.