


APPENDIX 1

OIL THIEVES CAMP



CAMP IS HIGHLY POLLUTED.

CRUDE RESERVIOR AT THE CAMP




THE RESERVIOR AT THE ILLEGAL REFINERY CAMP FROM ANOTHER ANGLE.

APPENDIX 2: PICTURES FROM JIV POINT.



2"VALVE AND PIPE LEADING TO THE CAMP.



PIPE REMOVED AND VALVE PEGGED.



REPAIRED SPILL POINT.



REPAIRED AND WRAPPED.