

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT



Fig A: Incident Area




Fig B: The Leak Point



Fig C: Containment Pit



Fig D: Condensate Impacted Area



Fig E&F: Incident facility during repair




Fig G: Incident Facility after repair