

CTURE TAKEN AT SITE



PIC 1. On Excavation



Pic 2. 2" Valve on found at 12 'O'clock Position



Pic 3.Repair work

