

PICTURES TAKEN AT SITE:

SPILL POINT BEFORE EXCAVATION:fig1



SPILL POINT DURING EXCAVATION:fig2



SPILL POINT AFTER REPAIRS:fig3

