

PICTURES TAKEN AT SITE:

AREA IMPACTED: fig1



SPILL POINT AFTER EXCAVATION: fig2



SPILL POINT AFTER REPAIRS: fig3

