

PHOTOGRAPH TAKEN DURING THE JOINT INVISITIGATION VISIT AT ELEPA



THE SPILL POINT AFTER EXCAVATION



THE SPILL POINT AFTER REPAIRS