

PHOTOGRAHS TAKEN DURING THE JOINT INVESTIGATION VISIT.



The area were the gas escape through a pin hole leakage at Wellhead Flange Spool, as a result of corrosion.



An area view of Obama Wellhead 12 at Obama Flow Station