

INCIDENT NO: 2020/LAR/GLI/012



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOC

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) CHASCOUS EMISSION

3. Incident Details

- i. Date of Incident: 16/02/2020 ii. Date first reported: 16/02/2020
iii. Date of first investigation: 17/02/2020
iv. Date of follow-up investigation:
v. Time investigation started: 15:50 HRS
vi. Estimated quantity spilled: N/A

4. Site Details

- i. Site/Location: OBIAFU 40T FLOW LINE @ OMOKU ONELGA RIVERS STATION
ii. Position of Spill/Leak: 1 N = 05° 23' 24.0" E = 006° 38' 49.9"
2 N = 05° 23' 24.1" E = 006° 38' 49.5"
iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 0'Clock ☐ 10 0'Clock ☒ 2 0'Clock ☐ 3 0'Clock
☐ 4 0'Clock ☒ 5 0'Clock ☐ 6 0'Clock 2.30 - 8 0'clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) CAS

iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify)