

PICTURE TAKEN AT SITE



PIC 1: Before excavation



Pic 2: After excavation 3" Ball valve found.



Pic 3: Repair work