

PICTURE TAKEN AT SITE



PIC 1. On Arrival



Pic 2: 2" Valve on found at 12 'O'clock Position



Pic 3. Repair work



Pic 4: Repair Work