

APPENDIX A

PHOTOGRAPHS TAKEN DURING JIV AT 6" OGBOINBIRI/TEBIDABA PIPELINE AT KEMEBIAMA IN SOUTHERN LOCAL GOVERNMENT AREA OF BAYELSA STATE.




BEFORE EXCAVATION



**SPILL POINT (AFTER EXCAVATION)
HACKSAW CUTS**



REPAIR POINT (WRAPPED)



IMPACTED ENVIRONMENT