

APPENDIX A

PHOTOGRAPHS TAKEN DURING JIV AT 6" Deep 6 Ogboinbiri Flowline At Ogboinbiri In Southern Local Government Area Of Bayelsa State.



GASEOUS EMISSION FROM SPILL POINT



THREE HACKSAW CUTS ON THE FLOWLINE



REPAIR POINT (WRAPPED)

WITHERED VEGETATION