

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT



Fig A: Incident Area on arrival of the JIT




Fig B: Incident Facility after excavation



Fig C: Incident facility during repairs



Fig D: Old crude/impact sighted by JIT within & outside RoW