

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT



Fig A: Incident Area on arrival of the JIT



Fig B: Incident Facility after excavation



Fig C: Incident facility during repairs



Fig D: Adjoining environment