



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY **JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIA AGIP OIL COMPANY LTD
2. Type of Complaint/Incident:
 - ☒ Oil Pollution
 - ☒ Fire/Explosion
 - ☒ Drilling Mud/Chemical Pollution
 - ☒ Others (Specify) _____
3. Incident Details
 - i. Date of Incident: 02/11/2019
 - ii. Date first reported: 02/11/2019
 - iii. Date of first investigation: 05/11/19
 - iv. Spill Incident No: 2019/SAR/002/2019
 - v. Date of follow-up investigation: 10/11/2019
 - vi. Time investigation started: 12:00hrs
 - vii. Estimated quantity spilled(bbls): 10 bbls
 - viii. Quantity Recovered: 8 bbls
4. Site Details A'Chugh Creek well 5 flowline @ Egbens Anglabiri
 - i. Site/Location: _____
 - ii. State: Bayelsa
 - iii. L.G.A: Shemina
 - iv. Spill Co-Ordinates: N(m): 04° 51' 07.7"
E(m): 005° 41' 24.4"
 - v. Spill area
 - ☒ Land
 - ☒ Swamp
 - ☒ Freshwater
 - ☒ Mangrove
 - ☒ Coastline
 - ☒ Near shore
 - ☒ Offshore
 - ☒ Others (specify) _____
 - iv. Structural Controls in Place
 - ☒ Boom
 - ☒ Trenches
 - ☒ Bund wall
 - ☒ Sorbents
 - ☒ Others (specify) _____
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☒ 12 O' Clock
 - ☒ 10 O' Clock
 - ☒ 2 O' Clock
 - ☒ 3 O' Clock
 - ☒ 4 O' Clock
 - ☒ 5 O' Clock
 - ☒ 6 O' Clock
 - ii. Type of Oil contaminant
 - ☒ Crude Oil
 - ☒ Condensate
 - ☒ Chemicals
 - ☒ Refined Products
 - ☒ Others (specify) _____
 - iii. Facility
 - ☒ Pipeline
 - ☒ Flow line
 - ☒ Wellhead
 - ☒ Manifold
 - ☒ Flow Station
 - ☒ Rig
 - ☒ Storage Tank
 - ☒ Compressor Plant
 - ☒ Others (specify) _____
 - iv. Cause of Spill
 - ☒ Corrosion
 - ☒ Equipment Failure
 - ☒ Third Party Interference
 - ☒ Accident



6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
☐ Others (specify) Stole LIME

ii. Nature of impact

- ☒ Oil stained vegetation
☒ Oil stained fishing nets
☒ Dead floating fishes
☒ Dead floating crabs
☒ Withering of vegetation
☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
☒ Fish Farm/ Pond
☒ Fishing Net
☒ Makeshift
☒ Permanent
☒ Others

8. Extent of Impact

a) Community (indicate name)

i. ECBEMA - ANCALABIRI

ii.

iii.

iv.

b) Land (indicate area in m²)

i.

ii.

iii.

iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken. NO APPC CABLE

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation. Urgent clean up required.
Naoe should be requested to sectionally
replace the flowline to avoid another incident.

13. Time investigation ended. 15:35 HRS.