

APPENDIX A:

PHOTOGRAPHS TAKEN DURING JIV AT 6" AZUZUAMA 6 FLOWLINE AT KEME-EBIAMA IN SOUTHERN IJAW LOCAL GOVERNMENT AREA OF BAYELSA STATE.



SPILL POINT



REPAIR POINT



INCIDENT ENVIRONMENT