

APPENDIX A:

PHOTOGRAPHS TAKEN DURING JIV AT 6" OGBOINBIRI/TEBIDABA PIPELINE AT OKPOTUWARI IN SOUTHERN IJAW LOCAL GOVERNMENT AREA OF BAYELSA STATE.



SPILL POINT



FIRE ON INCIDENT POINT



REPAIR POINT



IMPACTED AREA