

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT



Fig A: Incident Area on arrival of the JIT



Fig B: Incident facility (insulating joint)/ leak point



Fig C: Incident facility after tightening of the loose bolts