

APPENDIX A

PHOTOGRAPHS TAKEN DURING JIV AT 14" OGBOINBIRI /TEBIDABA PIPELINE AT
IKEBIRI SOUTHERN IJAW LOCAL GOVERNMENT AREA, BAYELSA STATE.



FIG. 1 SHOWING CRUDE OIL ON SPILL POINT

FIG.2 SHOWING CRUDE OIL ON SHALLOW DITCH



FIG.3 SHOWING 3" VALVE AT 12' O CLOCK

FIG.4 SHOWING THE SPILL POINT AFTER REPAIR