

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... NA

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation. SURVEILLANCE ON THE FACILITY SHOULD BE INTENSIFIED, OIL THEFT ATTACHMENT ON THE FACILITY SHOULD BE REMOVED AND REPAIR SHOULD BE EFFECTED

12. Time investigation ended 17.52 HRS

13. Name and Signature of Participants