

APPENDIX I

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT (JIV)



Fig A. SPILL POINT BEFORE EXCAVATION



Fig B. SPILL POINT AFTER REPAIR




Fig C. SPILL IMPACTED AREA



Fig D. SPILL POINT DURING EXCAVATION