

PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT



PICTURE SHOWING AFTER EXCAVATION OF THE SPILLED POINT, 2" VALVE INSTALLED FOR CRUDE OIL THEFT ACTIVITIES.



PICTURE SHOWING AFTER REPAIRS OF THE SPILLED POINT.