


APPENDIX A

PHOTOGRAPHS TAKEN DURING INSPECTION VISIT

SPILL POINT BEFORE EXCAVATION



SPILL POINT AFTER EXCAVATION



REPAIR WORK SHOWN



IMPACTED AREA SHOWN

