



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: THE NIGERIAN AGRI OIL COMPANY (NAGOC)
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
i. Date of Incident: 06/07/2022 ii. Date first reported: 06/07/2022
iii. Date of first investigation: 08/07/22 iv. Spill Incident No.: 2022 KAR/061/K
v. Date of follow-up investigation: 09/07/2022
vi. Time investigation started: 16:31 hrs
vii. Estimated quantity spilled(bbls): 193.83 viii. Quantity Recovered: ON-GOING
4. Site Details
i. Site/Location: 18" OBAWA/BRASS PLANE AT ODEBOKIRI
ii. State: LATISA iii. L.G.A.: NEWBE
iv. Spill Co-Ordinates: N(m): N 04° 28' 31.2"
E(m): 006° 15' 30.2"
v. Spill area
☐ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify).....
iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify).....



6. Impact of Incident

i Properties impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☐ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops
 ☒ Fish Farm/ Pond
 ☒ Fishing Net
 ☒ Makeshift
☒ Permanent
 ☒ Others

8. Extent of Impact

a) Community (indicate name)

- i. GOLBOKSRI
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i. 93,092-2036 m²
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken. *nil*

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation. *Facility shut down. Jid Completed on the 09/07/2022. Repairs of incident. Port on-going. Clean up of the impacted area require*

13. Time investigation ended. *16:31 Hrs*

14. Name and Signature of Participants

❖ NOSDRA

1. *UKAM BON EKUP* *09/07/2022*
- 2.
- 3.

❖ DPR *NUPRC*

1. *Sublin-Green, Sobonye* *09/07/22*
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

1. *ERIDAU LEIGHTA* *09/07/2022*
- 2.
- 3.

❖ COMPANY

1. *Benson OGB DACC RV* *09/07/2022*
2. *ARISIMO ORIZATE DACC RV* *09/07/2022*
3. *LEELEE LEAN REDFOX SURVEYOR* *09/07/2022*
- 4.
- 5.

❖ COMMUNITY

1. *TELIMAYE MAROMI OIL/GAS REMBOKINGDOM*
2. *Chief Magnus Tonish Ewelesuo*
- 3.
- 4.
- 5.