

APPENDIX A

PHOTOGRAPHS TAKEN DURING INSPECTION VISIT

SPILL POINT BEFORE EXCAVATION



SPILL POINT AFTER EXCAVATION

