


APPENDIX A

PHOTOGRAPHS TAKEN DURING A JOINT INVESTIGATION VISIT TO
24" OBAMA/TEBIDABA/BRASS PIPELINE AT
FANTUO/OKPOMA/EWOMA, NEMBE LOCAL GOVERNMENT AREA,
BAYELSA STATE.



PICTURE A: CORROSION AT 6 O' CLOCK POSITION. PICTURE B: CLAMPED SECTION OF THE PIPELINE.



PICTURE C: REPAIRED SECTION AFTER WRAPPING. PICTURE D: INCIDENT POINT AFTER BACKFILLING.