

APPENDIX A

PHOTOGRAPHS TAKEN DURING A JOINT INVESTIGATION VISIT TO 14" OGBOINBIRI-TEBIDABA PIPELINE AT OKPOTUWARI, SOUTHERN IJAW LOCAL GOVERNMENT AREA, BAYELSA STATE.



PICTURE 1: SHOWING 2" VALVE INSTALLED ON THE PIPELINE FOR OIL THEFT



PICTURE 2: SHOWING THE INCIDENT POINT AFTER REPAIR