

APPENDIX A
PHOTOGRAPHS TAKEN DURING A JOINT INVESTIGATION VISIT TO
18" TEBIDABA/BRASS PIPELINE AT KALATORU, SOUTHERN IJAW
LOCAL GOVERNMENT AREA, BAYELSA STATE.



PICTURE 1: SHOWING INSTALLED 3" VALVE AT POINT A.



PICTURE 2: SHOWING POINT A AFTER REPAIRS



PICTURE 3: SHOWING INCIDENT POINT B.



PICTURE 4: SHOWING POINT B AFTER REPAIRS