

**PHOTOGRAPHS TAKEN DURING JIV AT 18"TEBIDABA/BRASS PIPELINE AT MBIKIBA
SOUTHERN IJAW LOCAL GOVERNMENT AREA, BAYELSA STATE.**



FIG. 1 SHOWING SPILL POINT (BEFORE REPAIR)



FIG.2 Incident facility after exposure 6" inch valve




FIG.3 SHOWING SPILL POINT (AFTER REPAIR)



FIG.4 SHOWING SPILL POINT (AFTER BACK FILLED)