

APPENDIX A
PHOTOGRAPHS TAKEN DURING JIV AT 18"TEBIDABA/BRASS PIPELINE AT
MBIKIBA SOUTHERN IJAW LOCAL GOVERNMENT AREA, BAYELSA STATE.



FIG. 1 SHOWING SPILL POINT (BEFORE REPAIR)



FIG.2 SHOWING SPILL POINT (AFTER REPAIR)




FIG.3 SHOWING BACKFILL