


APPENDIX A:

*PHOTOGRAPHS TAKEN DURING JIV AT 6" OGBOINBIRI/TEBIDABA PIPELIE AT OKPOTUWARI
IN SOUTHERN IJAW LOCAL GOVERNMENT AREA OF BAYELSA STATE*




SPILL POINT BEFORE EXCAVATION



SPILL POINT



REPAIR POINT



IMPACTED AREA