

APPENDIX A:

PHOTOGRAPHS TAKEN DURING JIV AT 14" OGBOINBIRI/TEBIDABA PIPELINE AT KEME-EBIAMA
IN SOUTHERN IJAW LOCAL GOVERNMENT AREA OF BAYELSA STATE



SPILL POINT BEFORE EXCAVATION



SPILL POINT (INSTALLED 2" VALVE)



REPAIR POINT



IMPACTED AREA