

APPENDIX A

PICTURES TAKEN DURING THE JOINT INVESTIGATION VISIT AT 18" TEBIDABA/BRASS PIPELINE AT LAGOSGBENE, SOUTHERN IJAW LOCAL GOVERNMENT, BAYELSA STATE.



PICTURE 1 FROM LEFT: SHOWING A 15 MM INCISION MADE WITH HACKSAW BY VANDALS ON A PREVIOUSLY CONED INCIDENT POINT.

PICTURE 2: SHOWING THE INCIDENT POINT AFTER REPAIR .