

File No 800485



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 21/12/2022 ii. Date first reported: 22/12/2022
iii. Date of first investigation: 20/01/2023
iv. Date of follow-up investigation:
v. Time investigation started: 13:43 hrs
vi. Estimated quantity spilled: low Leak

4. Site Details

- i. Site/Location: 24" Bonny-Bonny Tap @ Otokolonvie
ii. Position of Spill/Leak: N 4.4973097 E 7.2159499
iii. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 o'Clock ☐ 10 o'Clock ☐ 2 o'Clock ☐ 3 o'Clock
☐ 4 o'Clock ☐ 5 o'Clock ☐ 6 o'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify) 6" valve seen installed @ road for
shaft propose.

Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Vulnerable Objects ☐ Others (specify) _____

n/a

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating debris
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (specify) _____

n/a

iii. Delimitation of Impacted area

☐ Within Company's facility/RCVW

☐ Outside Company's facility/RCVW

n/a

7. Extent of Impact

(a) Community (Indicate names)

(b) Land (Indicate area in m²)

- i. _____
 ii. _____
 iii. _____
 iv. _____

(c) Creek/Creek bed

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... *n/a*

10. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation...

*6th ball valve seen installed on PK E 12 o'clock
portion of left pipe. Inspected down by and saw well-
since it needed IPDE should fix the pipeline*

12. Time Investigation ended..... *14:20 hrs*

13. Name and Signature of Participants