

2023/LAR/114



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NADOC

2. Type of Complaint/Incident:

- ☒ Oil Pollution
 ☒ Fire/Explosion
 ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify) nil

3. Incident Details

- i. Date of Incident: 09/04/2023 ii. Date first reported: Nil
 iii. Date of first investigation: 09/04/2023
 iv. Date of follow-up investigation: Nil
 v. Time investigation started: 13.00 HRS
 vi. Estimated quantity spilled: 33.2 Bbls

4. Site Details

- i. Site/Location: 18" Ebocha-Ogboke Pipeline (5) Owerre Community Area, Rivers State
 ii. Position of Spill/Leak: N 05° 12' 03.4" E 006° 35' 25.0"
 iii. Spill area

- ☒ Land
 ☒ Swamp
 ☒ Freshwater
 ☒ Mangrove
 ☒ Coastline
☒ Near shore
☒ Offshore
☒ Others (Specify) nil

iv. Structural Controls in Place

- ☒ Boom
☒ Trenches
☒ Bund Wall
☒ Sorbents
☒ Others (Specify) nil

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock
☒ 10 0'Clock
☒ 2 0'Clock
☒ 3 0'Clock
☒ 4 0'Clock
☒ 5 0'Clock
☒ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil
☒ Condensate
☒ Chemicals
☒ Refined Products
☒ Others (Specify) nil

iii. Facility

- ☒ Pipeline
☒ Flow Line
☒ Wellhead
☒ Manifold
☒ Flow Station
☒ Rig
☒ Storage Tank
☐ Compressor Plant
☒ Others (Specify) nil

iv. Cause of Spill

- ☒ Corrosion
☒ Equipment Failure
☒ Third Party Interference
☒ Accident
☒ Operational Error
☒ Others (Specify) nil

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks
☒ Drilled Holes
☒ Blasting
☒ Theft
☒ Acid
☒ Others (Specify) nil

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (Specify) nd

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
Dead floating crabs Withering of vegetation Others (Specify) nd

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

- i. i. 1670.00m²
ii. ii.
iii. iii.
iv. iv.

(c) Creek/Creek lets

☒ Tidal

☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☒ Tidal

☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☒ Tidal

☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☒ Tidal

☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... *nil*

10. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation. *The company should improve the surveillance activity on the facility and clean-up should be carried-out immediately. Repair should be effected immediately.*

12. Time Investigation ended.....