



14/11/2023

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: Nigerian Pipeline/Storage Company (NPSC)
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 30/05/2023 ii. Date first reported: 30/05/2023
iii. Date of first investigation: 01/06/2023
iv. Date of follow-up investigation:.....
v. Time investigation started: 1056 HOURS
vi. Estimated quantity spilled: NOT AVAILABLE (NOT QUANTIFIABLE)
4. Site Details
i. Site/Location: IJEGUN, FIRE JUNCTION, IJEDODO
ii. Position of Spill/Leak: DUMP SITE, AROUND HOLY MESSIAH (CHURCH)
IJE DODO ROAD
iii. Spill area
☒ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
iv. Structural Controls in Place
☐ Boom ☒ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☒ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☒ Refined Products
☐ Others (specify).....
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
iv. Cause Of Spill
☒ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
v. Visible Sign of Third Party Interference N/A
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify)..... N/A

ii. Nature of impact

☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Oil rs..... N/A

iii. Delineation of impacted area

☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

b) Land (indicate area in m²)

i. i.
 ii. ii.
 iii. iii.
 iv. iv.

b) Creeks/Creeklets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....²⁰

10. Investigation carried out by

☒Foot ☐Boat ☐Aircraft

11. Remarks/Recommendation..... The pipes have been replaced and activities are back to normal in the area. The Right of way is also well secured.

12. Time investigation ended..... 1130 hours -

13. Name and Signature of Participants

❖ NOSDRA

OSDRA

1. Engr. Lueng A delodun
2. Ayeni I Peoluwa
3. Azike K. Chigoba

Chlorine

DPR

2.

3.

❖ STATE MINISTRY OF ENVIRONMENT

1.

4

3.

❖ LOCAL GOVERNMENT COUNCIL

1.

2.

3)

❖ COMPANY NNPC / NPSC

1. Jacob J. Gongden
2. Okporiri Vincent
3. Engr. Makinde, O-M

~~8~~
- $\sqrt{10}$ ~~NA~~

❖ COMMUNITY

1. Godwin Odinoke
2. Ofor Michael
- 3.

[Handwritten signature]