

INCIDENT NUMBER - 2023-1224585



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field.

1. Company: SPDC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify) THEFT POINT INSTALLATION

3. Incident Details

- i. Date of Incident: 02/06/2023 ii. Date first reported: 23/06/2023
iii. Date of first investigation: 02/07/2023
iv. Date of follow-up investigation: _____
v. Time investigation started: 14:52 HRS
vi. Estimated quantity spilled: NON-LEAK POINT

4. Site Details

- i. Site/Location: 20th NEW KOLOCREEK - RUMUKPE PL AT ODAU, ABUA/ODAWA LGAs
ii. Position of Spill/Leak: N 4.927395 E 6.431427

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify) NO SPILL

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) N/A

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify) _____

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) _____

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (Specify) 2nd BALL VALVE INSTALLED ON THE PIPELINE AT 12 O'CLOCK POSITION BY UNKNOWN PERSON(S) FOR OIL THEFT ACTIVITY

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) *N/A*

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) *N/A*

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

i. *ODTU*

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i. *non-leak point*

ii.

iii.

iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[diagonal line]</i>	<i>[diagonal line]</i>	<i>[diagonal line]</i>	<i>[diagonal line]</i>

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[diagonal line]</i>	<i>[diagonal line]</i>	<i>[diagonal line]</i>	<i>[diagonal line]</i>

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[diagonal line]</i>	<i>[diagonal line]</i>	<i>[diagonal line]</i>	<i>[diagonal line]</i>

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[diagonal line]</i>	<i>[diagonal line]</i>	<i>[diagonal line]</i>	<i>[diagonal line]</i>

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... *N/A*

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....

*Repair of the affected pont
should be carried out immediately. SPDC
should improve surveillance on US facility ROW.*

12. Time Investigation ended..... *15:27 HRS*

13. N/A